

~~SECRET~~

~~RESTRICTED~~

44-9-8-2013

176

TECHNICAL REPORT OF AIRCRAFT ACCIDENT CLASSIFICATION COMMITTEE

- (1) The Accident Classification Committee of 43rd Bomb Group (H) met on 12 September 1943 and determined the following:
- (2) Place, date, and time of accident Jackson, APO 929 0421, 7 September, 1943
 - (3) Aircraft station Jackson Org. 403rd Bomb Sq
 - (4) Aircraft model B24D A. C. No. 240682
 - (5) Date accepted from contractor Unknown
 - (6) Total hours .295.3 Hours since overhaul New
 - (7) Engine model R1830-43
 - (8) Engine A. C. No's 41-3776 L42-85869 R42-85942 R42-85983
 - (9) Extent of damage to engine(s) L. O. Salva L. I. Salva R. I. Salva R. O. Salva
 - (10) Total engine hours L. O. 532.2 L. I. 295.3 R. I. 295.3 R. O. 295.3
 - (11) Engine hours since overhaul L. O. 44.2 L. I. --- R. I. --- R. O. 29
 - (12) Purpose of flight Recon Mission
 - (13) Took off from Jackson Time 0420
 - (14) Weather at time of accident. (If weather was a causal factor attach copies of weather report and forecast for the flight.) ---.3 Stratua Cumulos, 3000 ft, Calm; Via 2 miles, Light Ground Fog
 - (27) 5

DUTY	IN COLUMN "DUTY" ENTER SYMBOLS AS FOLLOWS: C—Commander N—Navigator B—Bomber P—Pilot R—Radio operator O—Other crew CP—Co-pilot E—Engineer X—Passenger OB—Observer G—Gunner PH—Photographer	RESULTS TO PERSONNEL				PER- SONNEL ERROR	PILOT ERROR	% CAUSES
		A	B	C	D			
	Name, rank, and Army status, as: Regular Army, Res. ext., Res. Inact., etc.	Major Injury	Minor Injury	No Injury	Used parachute			
6/ P	Howard J. Wood, F/O, AUS 92	X	4	-	-			Error of judgment,
6/ CP	Howard R. Thomas, 1st Lt, EAD 1	X	4	-	-			Poor technique,
6/ N	Ralph M. Hart, 2nd Lt, EAD 1	X	4	-	-			Disobedience of orders,
6/ B	Robert G. McDonald, 2nd Lt, EAD 1	X	4	-	-			Carelessness or negligence,
6/ E	Charles P. Seip, T/Sgt., RA 20	X	4	-	-			Miscellaneous,
6/ AE	John Hrywnak, S/Sgt, AUS 20	X	4	-	-			Supervisory personnel,
7/ R	Hyman Silverstein, T/Sgt., AUS 20	X	4	-	-			Maintenance personnel,
7/ AR	Joel L. Herndon, S/Sgt., AUS 20	X	4	-	-			Other personnel,
7/ G	Donald F. Wilcott, S/Sgt, AUS 20	X	4	-	-			Fuel system,
7/ G	Samuel M. Wilkinson, S/Sgt., AUS 20	X	4	-	-			Cooling system,
7/ V	Samuel B. White, Sgt., RA 20	X	4	-	-			Ignition system,
7/ 3	AUSTRALIAN INFANTRY man (Number UNKNOWN)	X	4	-	-			Lubrication system,
								Engine structure,
								Propeller and propeller accessories,
								Engine control system,
								Miscellaneous (specify),
								Undetermined,
								Flight control system,
								Movable surfaces,
								Stabilizing surfaces; struts, wires, and fittings,
								Wings; struts, wires, and fittings,
								Landing gear, struts, wires, fittings, and retract. mech.
								Wheels, tires, and brakes,
								Fuselage, engine mount and fittings,
								Cowling, fairing, and fittings,
								Tail wheel assembly and skid,
								Miscellaneous (specify),
								Undetermined,
								Handling qualities,
								Instruments,
								Miscellaneous equipment (specify),
								10
								Weather,
								Darkness,
								Airport or terrain,
								Other,
								Undetermined,

(Explain any unsuccessful parachute jump by attachment)

NATURE (Check one only)	
DAMAGE TO AIRCRAFT (Less power plant)	A—Collisions in full flight with other aircraft, B—Collisions in full flight with objects other than aircraft, C—Spins or stalls following engine failure, D—Spins or stalls without engine failure, E (1)—Emergency forced landings, E (2)—Deferred forced landings, F—Landing accidents, G—Take-off accidents, H—Taxiing accidents, I (1)—Flames in the air, I (2)—Fires on the ground, J—Structural failure, K—Miscellaneous, L—Undetermined,
A—Complete wreck,	X
B—Major overhaul,	
C—Major replacement,	G
D—Minor damage,	
E—No damage,	

~~SECRET~~

~~SECRET~~

RESTRICTED

SECRET

(28) PILOT'S STATEMENT (state how the accident occurred, giving all details as to conditions, causes, and influencing factors):

RESTRICTED

Signature

Pilot.

(29) STATEMENT OF ACCIDENT CLASSIFICATION COMMITTEE (give complete causal statement, amplifying the pilot's statement where necessary to explain the causes):

SEE ATTACHED LETTER FOR STATEMENT OF ACCIDENT CLASSIFICATION COMMITTEE.

(30) RECOMMENDATIONS:

Each member of the Committee has read and understands A. C. Circular No. 15-14, A. R. 95-120, and N. A. C. A. Report No. 576.

The above statement and recommendations, and the classification and analysis shown on the reverse hereof, are the consensus of opinion of this Committee.

Signed	JAY P. ROUSER	MAJOR	PRESIDENT
Signed	JEAN A. JACK	MAJOR	MEMBER
Signed	JOHN A. ROBERTSON	CAPTAIN	MEMBER

(31) REMARKS AND RECOMMENDATIONS (accomplish only if this report is initiated at other than the home station):

Station Date Signature

(32) REMARKS AND RECOMMENDATIONS:

ENCLOSURES (line out those not applicable):
 Airplane (Airship) Flight Report.
~~_____~~
~~_____~~
 Certificates of principal witnesses.
~~_____~~
~~_____~~
~~_____~~

Station ... A.P.O. 929 Date 19 September, 1943

Signature

HARRY J. HAWTHORNE, Lt. Col. ^{Commanding}

RESTRICTED

SECRET

SECRET

7 September, 1943

DATE

B24D1

STATION

AIRPLANE MODEL

Charles P. Seip, T/Sgt

OR AERIAL ENGINEER

43rd Bomb Gp (H)

GROUP NO. AND TYPE

403rd Bomb Sq (H)

SQUADRON NO. AND TYPE

240682 AIRPLANE SERIAL NO

RESTRICTED

THIS IS A TRUE READER COPY

DENNIS J. LOMBARDI, Capt., Air Corps Adjutant.

43rd Bomb Gp (H)

GROUP NO. AND TYPE

240682 AIRPLANE SERIAL NO

THIS IS A TRUE READER COPY

DENNIS J. LOMBARDI, Capt., Air Corps Adjutant.

PERS CLASS	PRINT PLAINLY — NAME — RANK — ORGANIZATION		USE AS DIRECTED LOCALLY	ALWAYS ENTER DUTY SYMBOLS. WHEN APPLICABLE, ENTER N-NIGHT OR I-INSTRUMENTER TIME FLOWN THEREUNDER				FLIGHT DATA	
	1	2		DUTY IN OR I	DUTY N OR I	DUTY N OR I	N OR I	TERMINALS AND MISSION	
17 T-252	Wood, Howard J.	F/O	CM	2				FROM:	
01 0-790734	Thomas, Howard E.	1st Lt	CP					TO:	JACKSON
C1 0-674188	Hart, Ralph E.	2nd Lt	N					MISSION	04 20
61 0-738996	McDonald, Robert G.	2nd Lt	B					FROM:	
20 7033077	Seip, Charles P.	T/Sgt	E					TO:	
38 333456669	Hytnak, John.	S/Sgt	AE					MISSION	04 21
38 31201941	Silverstein, Hyman	T/Sgt	R					FROM:	
38 34082449	Herndon, Joel L.	S/Sgt	AR					TO:	
38 16075243	Hilcott, Donald F.	S/Sgt	G					MISSION	NO OF LANES
38 33277954	Wilkinson, Samuel M.	S/Sgt	G					FROM:	
20 14044815	White, Samuel B.	Sgt	V					TO:	
<u>ALL KILLED</u>									
THIS IS A TRUE READER COPY									
<i>Dennis J. Lombardi</i>									
DENNIS J. LOMBARDI, Capt., Air Corps Adjutant.									
SECRET									

WAR DEPARTMENT
A F FORM NO 1
TENTATIVE 12-18-41

FLIGHT REPORT - OPERATIONS
SECRET

TRANSCRIBED:
 LEGIBLE AND CORRECT
 TOTAL FLIGHT
 OPEN FLIGHT
 CREW TIME
 ON FORMIA
 CHIEF CLERK

SECRET

HEADQUARTERS
FORTY THIRD BOMBARDMENT GROUP (H) ^{RECORDED} VPB/joc
OFFICE OF THE ORDNANCE OFFICER

"RESTRICTED"

APO 929,
10 Sept., 1943.

SUBJECT: Cause of Detonation of Fuzed Bombs in Airplane Crash.

TO : Commanding Officer, 43rd Bombardment Group (H), APO 929.

1. A B-24 airplane of the 403rd Bombardment Squadron, 43rd Bombardment Group crashed just beyond the end of the runway at Jackson Drome, at approximately 0430 hours on the morning of 8 Sept., 1943.

2. The plane carried four (4) 500# Demolition bombs with AN M103 nose fuzes and AN M101A1 tail fuzes, .025 sec. delay. The bombs were fuzed and the safety pins were in the fuzes.

3. Witnesses stated that the bombs exploded within a few seconds of the crash.

4. An investigation by the writer showed that the bombs exploded with a high order detonation by impact with the ground and not by the fire that resulted. The plane struck the ground on the side of a slope and there was some burned wreckage at this point. At a point about ten (10) yards farther up the hill near the top, there were three craters from five (5) to eight (8) yards apart and about ten (10) yards from more burned wreckage. There was no burned wreckage at the point where the bombs exploded.

5. The fourth bomb laying on the top of the hill not far from the craters had an armed nose fuze in it, having had the cap retaining the safety blocks knocked off. The tail fuze had the stem broken off but the part holding the inertia slug was in place and this fuze was not in an armed condition. The shear wire had not been broken in the nose fuze and both fuzes were removed by the writer.

6. It is the opinion of the writer that on impact with the ground, the bombs broke through the wreckage knocking off the caps of the nose fuzes that retain the safety blocks. On tumbling and rolling for the next few seconds, the striker head of three of them hit the ground and detonated the bombs. The striking head in the fuze of the fourth bomb did not hit the ground.

Vincent P. Berger
VINCENT P. BERGER,
Capt., Ord. Dept.,
Ordnance Officer.

"RESTRICTED"
SECRET

SECRET

"RESTRICTED"

STATEMENT OF ACCIDENT CLASSIFICATION COMMITTEE

After due investigation and interrogation of witnessing personnel the committee arrived at the following conclusion.

Pilot wood undertook the fateful take-off under instrument conditions and failed to climb to a sufficient altitude before lowering the nose of the aircraft to increase the airspeed. Going directly from contact to instrument flying in B-24 aircraft, immediately after take-off is trying, on the best of pilots, for flight instruments can very easily give erratic readings at the moment the aircraft becomes airborne.

Witnessing personnel stated that the take-off was normal in all respects up to the time the ship began to descend.

At approximately 1000 yards from the S.E. end of the runway, the aircraft struck three (3) trees continuing on its destructive flight into a small hill at which point the bombs exploded. Parts of the wreckage ploughed through four (4) Australian Infantry trucks loaded with personnel and equipment, resulting in a very high fatality list. No members of the combat crew survived the crash.

With all causal factors having been considered the committee affixes the error as follows: Pilot 90%, and weather 10%.

"RESTRICTED"

SECRET

SECRET

AIR FORCE
ARMED FORCES
Office of the Group Commander Milwaukee, WISCONSIN

1943, 17 September, 1943.

Subject: Technical Report of Aircraft Accident Classification Committee.
To : Commanding General, United States Army Air Forces, War Department,
Washington, D.C.

1. Transmitted herewith Report of Aircraft Accident Classification Committee, 43rd Bombardment Group (H), A.F.C. 929, of aircraft model B-24D1, A.S. No. 240622, assigned to 403rd Bombardment Squadron (H), this Group, which crashed at Jackson Aerodrome, A.F.C. 929, 8 September, 1943.

Frank J. Hawthorne
FRANK J. HAWTHORNE
Lieut. Colonel, Air Corps,
Commander.

1 Incl:
Report.

OCT
(43)

"RESINATED"

SECRET

Accident No.

44-9-8-503

Pilot's Name

Hood, Howard J. 70

- 07 Nature Group Take off
51 Specific Nature Collision with tree
29 Underlying Nature Maneuver of controls

90% 02 Cause Group Technique
Hood, Howard J.
27 Specific Cause Momentary lack of
proficiency
04 Underlying Cause Physical reaction
was slow: overcontrolled &
undercontrolled
01. 33 Cause Group Weather
85 Specific Cause Weather
31 Underlying Cause